

---

## Test Procedure for

# SAMPLING DELINEATOR AND OBJECT MARKER REFLECTOR UNITS AND BARRIER REFLECTORS



**TxDOT Designation: Tex-725-I**

**Effective Date: February 2015**

---

## 1. SCOPE

- 1.1 This test method outlines the procedure for sampling delineator reflector units, object marker reflector units, and barrier reflectors.
- 

## 2. SAMPLING INFORMATION

- 2.1 An authorized representative of the Department will select samples.
- 2.2 Select samples only from delineator reflector units, object marker reflector units, and barrier reflectors designated for use on Department projects.
- 

## 3. PROCEDURE

- 3.1 Sample only delineator reflector units, object marker reflector units, and barrier reflectors listed on the Material Producer List (MPL).
- 3.2 Sample at the following rates.
- Delineator reflector units (sizes 1 and 2)—minimum of 5 each
  - Type 1, 3, or 4 object marker reflector units—minimum of 1 each
  - Type 2 object marker reflector units (sizes 2, 3, and 4)—minimum of 5 each
  - Barrier reflectors—minimum of 5 each

**Note 1**—Obtain samples from the same lot/batch number for each type, size, and color.

---

## 4. TAGGING/ LABELING, DOCUMENTING, AND SHIPPING

- 4.1 Follow the procedures detailed in Tex-701-I.
- 4.2 Package samples carefully to prevent damage during transit.
-

---

**5.           ARCHIVED VERSIONS**

5.1           Archived versions are available.